

Southeast Community Portfolio Centre 15

Environmental Health 1509 Centre Street SW Calgary, Alberta T2G 2E6

Phone: (403) 943-8095 Fax: (403) 943-8056

www.calgaryhealthregion.ca/envhealth

EXECUTIVE OFFICER'S ORDER

TO: Phuong Thi Nguyen

75 McKenzie Lake Manor S.E. Calgary, Alberta T2Z 1Y1

(the "Owner")

And To: All Occupants (the "Occupants") of those premises located in Calgary, Alberta and

municipally described as:

75 McKenzie Lake Manor S.E.

Calgary, Alberta

RE: Those premises located in Calgary, Alberta and municipally described as:

75 McKenzie Lake Manor S.E.

Calgary, Alberta

WHEREAS, pursuant to section 62 of the Public Health Act Chapter P-37 of the Revised Statutes of Alberta 2000, an Executive Officer who, following an inspection, has reasonable and probable grounds to believe that a nuisance exists in or on the place that was the subject of the inspection or that the place or the owner of it or any other person is in contravention of this Act or the regulations, the Executive Officer may issue a written order

AND WHEREAS I, an Executive Officer of the Calgary Health Region, have inspected the above noted premises and found to exist the following conditions which are or might become injurious or dangerous to the public health or that might hinder the prevention or suppression of disease or are in contravention of the Housing Regulation and/or the Nuisance and General Sanitation Regulation promulgated pursuant to Section 66 of the Public Health Act, namely:

- Mould growth and conditions that support mould growth are evident within the premises.
 Excess heat and humidity produced during the plant growing activities are suitable conditions for mould growth. Mould growth is evident in the basement area on wooden structures.
- Combustion gases from furnace and hot water tank are being discharged into the premises.
 Combustion stacks from the furnace and hot water tank have been disconnected so that the products of combustion are venting directly into the dwelling.
- Electrical system has been tampered with and a large hole has been cored through the foundation wall for the bypass.

• Surfaces throughout the growing and mixing areas are contaminated from the use of chemical/fertilizer solutions. Surfaces throughout the remainder of the premises are dirty.

- Structural and interior damage is evident in the premises. The large hole created for the electrical bypass may impair the integrity of the structure.
- Rear attached deck is rotting and a large hole is present in the center.
- The on-deck hot tub is not secured and is full of mould.
- Electricity, natural gas and water services have been turned off

AND WHEREAS, by virtue of the foregoing, the above noted premises are hereby declared to be **unfit for human habitation**;

NOW THEREFORE, I hereby **ORDER** and **DIRECT**:

- 1. That the above noted premises be vacated immediately.
- 2. That the above noted premises be secured from any and all unauthorized entry.
- 3. That all putrescible matter be removed from the premises and properly disposed of.
- **4.** That **permission to enter be received in writing** from the undersigned or a designated alternate Executive Officer of the Calgary Health Region.
- **5.** That, if the above noted premises are to be reoccupied, the Owner immediately undertake and diligently pursue the completion of the following work in and about the above noted premises, namely:
 - a. Retain the services of an Environmental Health or Indoor Air Quality Consultant to:
 - (i) assess the conditions within the above noted premises including the carrying out of environmental air quality analyses of the interior spaces (including the attic, wall and floor cavities, and crawlspaces) for water and mould damage; and
 - (ii) prepare for review by Calgary Health Region a detailed assessment report and scope of work plan, including a hazardous materials audit and management plan.

Testing and reporting shall follow the requirements outlined in Calgary Health Region's Fungal Air Testing Protocol and must include extensive intrusive and destructive testing and shall and must include inspection and assessment of hidden cavities and surfaces such as, but not limited to, cutting access holes (or using boroscopes) into walls and ceilings, lifting carpets or vinyl sheet flooring, removing wallpaper for investigation purposes. The consultant's report shall describe, *inter alia*, the building construction, finishes, materials and components and the results of their investigations along with recommendations for restoration, repair, and the remediation as required for reoccupation of the building. The Consultant should have current, active membership in a related professional organization or certifying body and shall be first approved in writing by Calgary Health Region.

• Extensive intrusive testing must be performed throughout all perimeter walls to ensure no hidden moisture concerns or moulds exist between internal and external walls.

- b. Prior to performing any work inside the above noted premises apply for and obtain all permits and approvals required by law, including, but not limited to, Environmental Restoration, Electrical, Plumbing, Gas and/or Mechanical permits. (The Environmental Restoration permit may require that you obtain the services of a Professional Engineer (Alberta) to provide an intended Scope of Work report which shall describe the building construction, finishes, materials and components and the results of their investigations along with recommendations for restoration, repair, and remediation as required for reoccupation of the building. Any such Report shall be forwarded to Calgary Health Region.)
- c. Retain the services of contractors to make all structural, electrical, mechanical repairs necessary, all in compliance with applicable codes and regulations, and thereafter provide Calgary Health Region with a report or reports from such contractor or contractors confirming the work performed;
 - The borehole through the foundation wall must be properly repaired and must be sealed from the outside to prevent water infiltration into the premises. The repair must be inspected prior to backfilling the exterior excavation
 - NOTE THAT ALL CITY INSPECTIONS MUST BE PERFORMED PRIOR TO COVERING UP ANY REPAIR
- d. Retain the services of a restoration and mould remediation specialist, approved by Calgary Health Region, to remove and replace or clean, as required, any and all drywall, building materials, and finishing materials, or any other item that is or may be water damaged, infested with or damaged by mould or bacteria or otherwise contaminated with chemicals or other substances of concern, all in accordance with the direction required at item 4.a, above. (Reference should be made to Mould Guidelines for the Canadian Construction Industry located at www.cca-acc.com/mould/.)
 - All materials related to the plant growing operation that are remaining behind, including pots, soil, fans, lights, cutting tools, and general rubbish, shall be removed and disposed of
 - All furnishings and window coverings throughout shall be removed and professionally cleaned or disposed of and shall not be stored in an attached garage due to the chance of recontamination
 - All paneling, drywall, plywood, vapour barrier and insulation throughout the
 basement, including ceilings, shall be removed and disposed of and all wood
 framing shall be professionally assessed for suitability after thorough
 cleaning. Obviously damaged wood structures, especially floor plates, shall
 be removed and disposed of. All concrete basement walls and floors shall
 then be thoroughly washed with detergent and water and quickly dried. The
 concrete basement floor shall not be covered or painted until after
 remediation and air sampling is complete and has been accepted by Calgary
 Health Region

- All carpeting throughout the premises shall be professionally cleaned
- All remaining hard surfaces throughout, including but not limited to walls, floors, doors, cupboards, shall be thoroughly washed with detergent and water
- e. Ensure that additional, general renovation work, including painting, reinstallation of drywall and laying of new flooring and/or sub floors does not occur until suitable air sample results are received and submitted and the work identified at items 4.a, 4.b, 4c. and 4.d has been completed to the satisfaction of Calgary Health Region.
- f. Ensure that general renovation work, including painting, reinstallation of drywall and laying of new flooring and/or sub flooring is completed to the satisfaction of Calgary Health Region.
- g. Properly dispose of all chemicals and produce a valid manifest attesting to such proper disposal.
- h. Retain the services of a licensed furnace company to inspect and clean the furnace and all ducts within the premises. Furnace cleaning shall take place as a final step after the completion of all remediation work but before final air sampling. It is recommended that the furnace cleaning company be a member of the National Air Duct Cleaners Association or an equivalent professional body.
- i. Repair or remove the on-deck hot tub. Ensure the lid can be secured.
- j. Repair the attached rear deck to acceptable standards.
- k. Ensure that water, gas and electrical services are properly reinstated by the providers of such utility services.
- I. Provide a detailed remediation and repair report which includes copies of all disposal manifests for removed materials, invoices for new, replacement materials, work orders, receipts, results, photos, inspection certificates and any other documentation pertaining to the work required hereby to Calgary Health Region.
- m. Take any further steps in the interests of preserving and maintaining the health of any person who may, in the future, occupy the above noted premises as may be required by the Executive Officer.

That, until such time as the work referred to in paragraph 4 is completed to the satisfaction of the undersigned or by a designated alternate, the above noted premises shall remain vacant and shall be secured from unauthorized entry. Entry may be authorized only for the purposes of complying with this Order, and full personal protective equipment must be worn. Until otherwise directed by Calgary Health Region, full personal protective equipment must be worn by any person seeking entry.

The above conditions were noted at the time of inspection any may not necessarily reflect all deficiencies. You are advised that further repairs may be required to ensure full compliance of the Housing Regulation and/or the Nuisance and General Sanitation Regulation, or to prevent a Public Health Nuisance.

This order remains in effect until the nuisance has been corrected to the satisfaction of an Executive Officer of the Calgary Health Region. Failure to comply with this order will result in further action.

No person shall conceal, deface, destroy, or remove a notice posted pursuant to the Public Health Act.

Dated at Calgary, Alberta, this 7th day of September, 2007.

Vicki Wearmouth, CPHI(C)
Executive Officer/Public Health Inspector

Section 5(2) of the Public Health Act provides that a person who is directly affected by this Order and considers himself or herself aggrieved hereby may appeal the same to the Public Health Appeal Board, 21st Floor, Telus Plaza North Tower, 10025 Jasper Avenue, Edmonton AB T5J 1S6, within ten (10) days. The terms of this Order remain in effect notwithstanding the filing or proposed filing of any such appeal.

The Owner is advised that the Public Health Act empowers the Calgary Health Region to carry out the terms of this Order on the Owner's behalf and at the Owner's expense should the Owner fail to comply with the terms hereof.